Guildford Design Awards 2023 Entry Requirements RHS Garden Wisley – The Old Laboratory

1. Address of Scheme including postcode

The Old Laboratory RHS Garden Wisley Woking Surrey GU23 6QB

2. Category of Project

Conservation Project

3. Name of Client

The Royal Horticultural Society

4. Architect, Design Consultants or Artist

Responsible for all internal and external fabric repairs and alterations

Samir Khatri, Architect Partner Philip Hughes Associates Historic Building Conservation Consultants Old Manor Stables Tout Hill Wincanton Somerset BA9 9DL

Responsible for the internal exhibition design elements and furniture

Paul Davis, Managing Director Agenda Design Studio 1-4 108 Point Pleasant London SW18 1PP

5. Key contact - Email address, phone number, etc.

Vicky Hill-Patrick RHS Head of Estates South vickyhillpatrick@rhs.org.uk 07702104133 6. Brief description of the Project including key features of the design, maximum 1 page A4

The works consisted of:

- o Replacement boiler and heating systems
- \circ $\;$ Underpinning of failing structure at north end of the building
- Demolition of old arrivals, retail and café masking the car park facing elevation of the Old Laboratory Building
- Repair and conservation of all damaged and aging external fabric elements. Included the erection of new porch using historic photographs for design reference and repairing scars of where demolished building fixed to historic fabric
- Creation of the new external landscape
- Refurbishment of all interior office, storage and communal spaces
- Provision of fire compartmentation and separation throughout the building to conform with all relevant fire safety legislation
- \circ $\;$ Replacement and introduction of new security, fire and safety alarm systems throughout
- Creation of public exhibition spaces with full restoration of historic interiors and set design
- 7. Photographs of the completed project (include existing photographs, plans and elevations, as appropriate for the Conservation Project and Regeneration Project categories)



Wisley Laboratory 2023

Wisley Front of House Regeneration









c.1920





Porch Reconstruction 2021/22




c. 1920


1980s

External Fabric Repairs 2021





West Elevation Timber Repairs



South Elevation Timber Repairs

Lecture Room Internal Refurbishment and Exhibition Fit Out



c.1920







Laboratory Room Internal Refurbishment and Exhibition Fit Out



Gallery Internal Refurbishment and Exhibition Fit Out



Entrance Hall Internal Refurbishment and Exhibition Fit Out



Advisory Office Internal Refurbishment and Exhibition Fit Out

